



Call the indicated branch
for current pricing and availability.
01 = Mentor, 02 = Cincy, 03 = Taylor,
04 = Pittsburgh, 06 = Evansville
Perry, NAPP = North Atlantic

STATUS CODES
A = READY
B = IN PROCESS
C = "AS IS"

3/10/2009

DANA TORQUE CONVERTERS

ITEM #	PART#	MODEL	DESCRIPTION	EXCH PRICE	MPDF	NCRF	BRANCH	STATUS	SO#	AT
1	R286299	C272.5-49	CLARK CONVERTER	3,400	1,500	2,200	6	A		
2	R287644	C272.1-54	CLARK CONVERTER	3,400	1,500	2,200	6	A		69-7-3
3	R288062	C272.1-61	CLARK CONVERTER	3,400	1,500	2,200	6	A		69-7-3
4	R290135	C272.5-99	CLARK CONVERTER	3,400	1,500	2,220	2	C	26793	
5	R292397	C272.5-110	CLARK CONVERTER	3,400	1,500	2,200	2	A		25-1-1
6	CR283839	C273.1-28	CLARK CONVERTER	3,400	1,500	2,200	2	C	WG1052	
7	292916	C273-383	CLARK CONVERTER	3,400	1,500	2,200	6	A		69-7-3
8	R291302	C16702-21	CLARK CONVERTER	9,500	4,000	5,500	6	A		69-5-FLR
9	R290386	C8402-61	CLARK CONVERTER	6,850	4,500	1,800	6	C	WH1809	
10	R291660	CL8612-86	CLARK CONVERTER	7,500	4,500	2,000	6	C	WH1887	

DANA TRANSMISSIONS

12	R4262760	1102FT12362-200	CLARK POWER SHIFT	6,300	3,000	1,000	4	A		
13	426135300	1104FT12362-10	CLARK SEE 00426135300	0	0	0	2	NEW		DISASSEMBLED
14	426135300	1104FT12362-10	CLARK SEE 00426135300	0	0	0	US POWER	NEW	4 UNITS	SEE PAUL G.
15	CR4268379	1106FT12363-201	CLARK POWER SHIFT	6,300	3,000	1,000	US POWER	C	NEEDS	INSPECTION
16	4263879	1106FT12363-201	NEW UNIT	10,300	0	0	US POWER	NEW	10 UNITS	
17	4262770	1104FT12366-201	NEW UNITS	11,500	0	0	USPOWER	NEW		
18	R4262770	1106FT12363-201	CLARK POWER SHIFT	6,300	3,000	1,000	PERRY	A		SHOP RACKS
18	R4261473	1102FT12366-18	CLARK POWER SHIFT	6,300	3,000	1,000	2	B	WG1882	CONVERT
19	CR4261373	1102FT12366-22	CLARK POWER SHIFT	6,300	3,000	1,000	6	C		CORE
20	R4262128	1107T16000-19	CLARK POWER SHIFT	6,300	2,500	1,300	US POWER	A		
21	CR4262128	1107T16000-19	CLARK POWER SHIFT	6,300	2,500	1,300	US POWER	C	2 UNITS	NEED INSPECTION
22	R4263256	340FTE17310-21	CLARK POWER SHIFT T17	12,400	5,500	4,000	US POWER	A		
23	R289283	12.6HR18302-19	CLARK POWER SHIFT	7,500	3,000	1,000	2	C	23562	78-1-2
24	R289708	12.6HR18302-24	CLARK POWER SHIFT	7,500	3,000	1,000	6	A		
25	CR287547	12.2HR18326-16	CLARK POWER SHIFT	7,500	3,000	1,000	US POWER	C	NEEDS	INSPECTION
26	R289714	12.2HR18327-37	GETMAN	7,500	3,000	1,000	6	A		69-5-3
27	4263565	1201FT20314-100	NEW UNIT	14,500	0	0	US POWER	NEW		
28	4261617	120FT20326-10	NEW UNIT	16,500	0	0	US POWER	NEW		
29	R290672	13.9LFHR24658-5	GROVE SPEC	11,500	4,500	4,000	6	C		R291278 EXCEPT
30	R291278	13.9FLHR24658-10	LINK BELT	11,500	4,500	4,000	6	C		

DANA TRANSMISSIONS continued

31	R292173	13.7HRS32621-8	CLARK POWER SHIFT	11,750	5,500	4,800	US POWER	RUNNING TAKE OUT	SEE DON
32	R293522	13.7HRS32621-15	CLARK POWER SHIFT	11,750	5,500	4,800	US POWER	RUNNING TAKE OUT	SEE DON
33	R28480-9	R292083	DANA SIDE SUMP TRANS	9,800	5,500	3,500	6	A	69-8-4
34	R28480-6	R290299	DANA SIDE SUMP TRANS	9,800	5,500	3,500	6	C	WH1179 70-2-4
35	R288592	13HR28361-6	S/N159020ER	8,000	4,500	500	2	A	25760 25-4-2
36	R284232	R28621-8	GROVE SPEC	8,000	4,500	500	4	C	
37	R289615	4421-244	TAMROCK	0	0		2	C	25410
38	H405080-002	MOD 784	784-PEPEPP-F	0	0	0	US POWER	NEW UNITS	SEE QUIPWARE

DANA Axles and Differentials

39	CR213/142	213/142	DANA AXEL	0	0	0	PERRY	CALL DAVE ALLEN	WY1281	5 EA.
40	CR213/143	213/143	DANA AXEL	0	0	0	PERRY	CALL DAVE ALLEN	WY1282	5 EA.

1) The returned exchange unit is property of Great Lakes Power Products. It must be intact, free of cracked or broken housing.

2) The published NCRF (Non-Core Return Fee) is billed if core is not returned, or is different from original unit supplied.

3) The MPDF (Major Parts Damage Fee) will be determined upon disassembly by Great Lakes Power Products.

The following are considered Major Components TRANSMISSION HOUSING CLUTCH SHAFTS ALUMINUM COMPONENTS MISSING PARTS