



Call the indicated branch
for current pricing and availability.
01 = Mentor, 02 = Cincy, 03 = Taylor,
04 = Pittsburgh, 06 = Evansville
Perry, NAPP = North Atlantic

STATUS CODES
A = READY
B = IN PROCESS
C = "AS IS"

3/10/2009

SINGLE STAGE CONVERTER LIST

ITEM #	SPEC # PART #	MODEL	DESCRIPTION	SELL \$	MPDF	NCRF	BRANCH	STATUS	SO#
1	CR6C1300	6CO1300	200MS MISSING PARTS	0	0	0	2	C	WG1325
2	CR62823	6CO1504-1	MS335/ROBBED IMPELLER	6,500	5,000	9,600	2	C	WG1048
3	R95641	6CO1504-1	MS400	6,500	5,000	9,600	2	C	WG2228
4	R62028	6CO1504-1	MS280	6,500	5,000	9,600	2	A	WG1187
5	R97361	6CO1504-1	MS400	6,500	5,000	9,600	2	A	WG1157
6	R63973	6CO1512-1	MS280	6,500	5,000	9,600	2	C	WG1146
7	R60643	6C01512-1	MS 400 HAS 6" SHAFT	6,500	5,000	9,600	PERRY	C	25329
8	CR63972	6C01512-1	400MS	6,500	5,000	9,600	2	C	WG1700
9	CR97175	6F1307-2	MS400	0	0	0	2	C	WG1008
10	R64249	6F1509-1	MS280	0	0	0	4	A	
11	R60433	6F1514-1	MS280 LESS DRIVE RING	4,200	1,500	500	2	A	25577
12	CR61555	8FLW1605	RUNNING TAKEOUT MS370 REMOTE MOUNT	4,500	0	OUT RIGHT	2	C	WG1038
13	CR61555	8FLW1605	RUNNING TAKEOUT MS370 REMOTE MOUNT	4,500	0	OUT RIGHT	2	C	WG1330
14	R99751	8FLWB1801-1	8FLWB1801-1 SEE CR99752	0	0	0	6	C	FLOOR 1
15	R63559	4C02016-1	MS742	10,500	6,500	7,000	2	C	25674
16	CR62876	4C02016-1	400MS	10,500	6,500	7,000	2	C	WG1036

SINGLE STAGE CORE POLICY

- 1) The returned exchange unit core is the property of Great Lakes Power. It must be intact, free of cracked or broken housings.
- 2) The published NCRF (Non-Core Return Fee) is billed if core unit is not returned or is a different specification or model arrangement from original supplied.
- 3) MPDF on returned unit will be determined upon disassembly and inspection by Great Lakes Power Products. Specific "Major Parts Damage" will be deducted from the credit. The following items are considered "Major Parts Damage Fee".

Impeller Assembly, Turbin Assembly, Turbin Housing, Gearing, Shafts, Missing parts

* MPDF - Major Parts Damage Fee

** NCRF - Non-Core Return Fee